

MORMUGAO PORT TRUST
MARINE DEPARTMENT

Ref. No.: DC/S(21)/2016/04

Date: 8th Feb., 2016.

HARBOUR NOTICE NO. 04 (TEMP) 2016

The Channel Red light buoy **Nos. 2, 4, 6 & 8** are shifted **50.0 mtrs North** and the Green light buoy **Nos. 1, 3, 5 & 7** are shifted **50.0 mtrs South** from their existing original position.

Navigators are requested to centre the channel while sailing for safe Navigation.

The Buoy **No. 9** has been shifted about **60.0 Mtrs** towards the Mole light.

The above shifting arrangement has been carried out to facilitate the Capital Dredging work at this Port. On completion of Capital Dredging, the above buoys will be replaced to their respective Original position.

HARBOUR MASTER

To,
All Concerned

All Port Users/Agents

President,
Mormugao Fishing Trawler Association

President,
Mormugao Barge Owners Association

Fishery Survey of India, Mormugao, Goa

CISF/MPT

Copy to: Chairman's table
DC/FA&CAO/TM/CME/CE/Secretary/CMO
HM/All Pilots/CO(SS)/CO(PR)/Signal Station/Pilot Room/MS
Hindi Section .. for translation