

मुरगांव पत्तन न्यास  
समुद्री विभाग

Ref. No.: DC/S(21)/2015/06

Date: 23<sup>rd</sup> June, 2015

**HARBOUR NOTICE NO. 06 (TEMP) 2015**

This is to inform all concerned that Ameer Shoal Buoy is Adrift and Missing from its position about 15° 25'.72 N and 73° 46'.72 E.

All Mariners to exercise due caution while navigating in those areas.

Sd/-

(Capt. Paramjeet Singh Saini)  
HARBOUR MASTER

To,  
All Concerned  
Shipping Agents

c.c. to: Communication Officer : Please advise Signaller-cum-RTO to inform the above message to all the Ships calling at this Port and proper entries should be made in the Shipping Log Book.

c.c. to: The President, Mormugao Fishing Trawlers/Vessels Association

c.c. to: The President, Mormugao Barge Owners Association

c.c. to: The President, Mormugao Passenger Launches Owners Association

c.c. to: Fisheries Survey of India, Alto Jetty, Near Police Station, Bogda, Mormugao

c.c. to: Chairman's table

c.c. to: All HOD's

c.c. to: CO(PR)/Marine Department