

मुरगांव पत्तन न्यास
समुद्री विभाग

सं. सं.: DC/S-(21)/2016/10

Date: 17/03/2016

HARBOUR NOTICE NO. 10 (TEMP) 2016

Sub: Buoy No. 1.

It is to inform all concerned that Bouy No. 1 had shifted from its original position and dragged southwards.

It has been removed now and will be deployed once new chains are fixed.

HARBOUR MASTER

To,

- 1) All Shipping Agents
- 2) The President, Mormugao Fishing Trawlers Association
- 3) The President, Mormugao Barge Owners Association
- 4) The President, Mormugao Passenger Launches Owners Association
- 5) Fisheries Survey of India, Alto Jetty, Near Police Station, Bogda, Mormugao

c.c. to: Communication Officer : Please advise Signaller-cum-RTO to inform the above message to all the Ships calling at this Port and proper entries should be made in the Shipping Log Book.

c.c. to: Dy. Chairman/Chairman's table

c.c. to: DC/Director (P&MS)/FA&CAO/Commander CISF/CE/CME/TM/Secretary/CMO
All Pilots/HM/CO(SS)/Port Signal Station/Pilot Room/MS/CO(PR)/SE(M)/SO(M)