

मुरगांव पत्तन न्यास
समुद्री विभाग

सं. सं.: DC/S-(21)/2016/11

Date: 17/03/2016

HARBOUR NOTICE NO. 11 (TEMP) 2016

Sub: Drum bouy with red flashing light.

It is to inform all concerned that the drum buoy with red flashing light on top of the wreck mother pearl has been stolen and missing from its position. It is requested to all navigators to exercise due caution while navigating in and out of Zuari channel.

HARBOUR MASTER

To,

- 1) All Shipping Agents
- 2) The President, Mormugao Fishing Trawlers Association
- 3) The President, Mormugao Barge Owners Association
- 4) The President, Mormugao Passenger Launches Owners Association
- 5) Fisheries Survey of India, Alto Jetty, Near Police Station, Bogda, Mormugao

c.c. to: Communication Officer : Please advise Signaller-cum-RTO to inform the above message to all the Ships calling at this Port and proper entries should be made in the Shipping Log Book.

c.c. to: Dy. Chairman/Chairman's table

c.c. to: DC/Director (P&MS)/FA&CAO/Commander CISF/CE/CME/TM/Secretary/CMO
All Pilots/HM/CO(SS)/Port Signal Station/Pilot Room/MS/CO(PR)/SE(M)/SO(M)